SAFETY ALERT

06 December 2016

A powerboard was found to have a fault in its illuminated on/off switch, causing a minor electrical shock to a member of staff.

Sansai 4-way power board (pictured after the on/off switch cover was removed)

BACKGROUND

A member of staff receiei el e2J - re2Jal e2(ho9(e2wille(epise)s2en)1.1.6(r)76ec)5ff9(e2(w)13-6.-)Tj - re2Jh o.5(7)14 oards in the area were found, under close inspection, to have cracks to

oplied by Complete Office Supply (COS), was found to have the same a shock risk if the switch cracks.

WHAT WAS DONE WELL

- x All Sansai powerboards in the area were quarantined.
- x UNSW Procurement was notified in order to liaise with the UNSW preferred supplier.
- x The manufacturer was informed of the incident.
- x Product Safety Australia was notified.

ACTION FOR LOCAL AREAS TO TAKE

- x Carefully inspect all powerboards with illuminated on/off switches for cracks/faults. Dispose of any found to be damaged.
- x Avoid use of any powerboard with illuminated on/off switches.

The quality of the Sansai powerboard is still under investigation.

Further information:	Corresponding author for this alert:
Contact your Faculty Health, Safety Environment Coordinator	b.farrell@unsw.edu.au
www.safety.unsw.edu.au	